

**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

<b>ITEM #</b>	<b>PHOTO TITLE</b>	<b>SUBJECT</b>	<b>DATE(S)</b>	<b>LOCATION</b>
<input type="checkbox"/> 1	Brock Street, Fort William	View of street	March 16, 1915	4876
<input type="checkbox"/> 2	[Mechanism with Clock]	Unidentified mechanism with a clock on it		4876
<input type="checkbox"/> 3	[Four Men with Dog]	Four unidentified gentlemen and a dog seated outside a building - portion of sign shown but not enough visible to make out what it says		4876
<input type="checkbox"/> 4	[Trestle or Bridge]	Unidentified scene, some sort of trestle or bridge, possibly under construction, large stack next to it and horses and wagon on it		4876
<input type="checkbox"/> 5	Great Lakes Dredging Co.	Great Lakes Dredging Co. - ship and water in foreground		4876
<input type="checkbox"/> 6	[Men Working]	Men at work in an unidentified area		4876
<input type="checkbox"/> 7	[Men Working]	Two men at work on some sort of large pipe, see Accession 1992-30 Item 11 - same area		4876
<input type="checkbox"/> 8	[Gentlemen in front of Street Car]	Group of well dressed gentlemen standing in front of street car		4876
<input type="checkbox"/> 9	[Group of Men]	Group of men outside of an unidentified building - water in foreground		4876
<input type="checkbox"/> 10	[Construction]	Unidentified large building under repair or construction, looks like railroad tracks in foreground, same area as Accession 1992-30 Item 24		4876
<input type="checkbox"/> 11	[Men Working]	Two men working on some sort of large pipe, looks like same place as Accession 1992-30 Item 7		4876
<input type="checkbox"/> 12	[Construction]	Some type of construction		4876

*Note: Negative available when checkmark in box.*

**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

<b>ITEM #</b>	<b>PHOTO TITLE</b>	<b>SUBJECT</b>	<b>DATE(S)</b>	<b>LOCATION</b>
<input type="checkbox"/> 13	[Dam]	Looks like a dam		4876
<input type="checkbox"/> 14	[Vehicles on Street]	Line of vehicles going down street, similar to Accession 1992-30 Item 15		4876
<input type="checkbox"/> 15	[Vehicles on Street]	Line of vehicles going down street, similar to Accession 1992-30 Item 14		4876
<input type="checkbox"/> 16	[Construction Site]	Unidentified construction site		4876
<input type="checkbox"/> 17	[Construction Site]	Unidentified construction site		4876
<input type="checkbox"/> 18	[Construction Site]	Unidentified construction site		4876
<input type="checkbox"/> 19	Great Lakes Dredging	Great Lakes Dredging		4876
<input type="checkbox"/> 20	[Building on Lake]	Small wooden building on edge of lake		4876
<input type="checkbox"/> 21	[Men at Construction Site]	Two men standing at an unidentified construction site		4876
<input type="checkbox"/> 22	[Six Men]	Six unidentified men posed in an unidentified area		4876
<input type="checkbox"/> 23	[Dredging Apparatus]	Looks like a dredging apparatus - possibly Great Lakes Dredging		4876
<input type="checkbox"/> 24	[Construction of Building]	Unidentified building under construction, railroad tracks in foreground, same area as Accession 1992-30 Item 10		4876
<input type="checkbox"/> 25	[Construction Site]	Unidentified construction site		4876
<input type="checkbox"/> 26	[Houses and Buildings]	View of houses and buildings, mountain in background		4876
<input type="checkbox"/> 27	[Men Looking at Pipes]	Two Men looking at large pipes in an unidentified area		4876
<input type="checkbox"/> 28	Brown Street, Fort William	View of street	March 16, 1915	4876

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 29	[Neebing River Flood]	High water - river water crossing Cummings Street	Sep. 22, 1941	4877
<input type="checkbox"/> 30	[Neebing River Flood]	High water Neebing River - looking from McMillan and Southern towards Simpson Street Bridge	Sep. 22, 1941	4877
<input type="checkbox"/> 31	[Neebing River Flood]	High water Neebing River, Royal Fort Tourist Grounds corner of May and Southern	Sep. 22, 1941	4877
<input type="checkbox"/> 32	[Neebing River Flood]	High Water Neebing River - looking east on Northern Avenue from May Street	Sep. 22, 1941	4877
<input type="checkbox"/> 33	Neebing River Flood	Looking east on William Street from Alexander Street, these photographs are numbered 33.1 and 33.2	Sep. 22, 1941	4877
<input type="checkbox"/> 34	Neebing River Flood	Up-stream side Cameron Street Bridge, these photographs are numbered 34.1 and 34.2	Sep. 22, 1941	4877
<input type="checkbox"/> 35	Neebing River Flood	Just east of Vickers Street Bridge, taken from John Street - houses on Vickers Street, these photographs are numbered 35.1 and 35.2	Sep. 22, 1941	4877
<input type="checkbox"/> 36	Neebing River [Flood]	River water on Balmoral Street	Sep. 22, 1941	4877
<input type="checkbox"/> 37	Neebing River Flood	At Vickers Street Bridge	Sep. 22, 1941	4877
<input type="checkbox"/> 38	Neebing River Flood	Just east of May Street Bridge, these photographs are numbered 38.1 and 38.2	Sep. 22, 1941	4877
<input type="checkbox"/> 39	Neebing River [Flood]	Neebing River Bridge - Neebing Avenue under water, unidentified individual holding a measuring device in the water	Sep. 22, 1941	4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 40	[Flood]	Unidentified flooded area - possibly upper side of Cameron Street Bridge - see Accession 1992-30 Item 34		4877
<input type="checkbox"/> 41	[Flood]	Unidentified flooded area, looks like a walking bridge, looks like same area as Accession 1992-30 Item 42 - just a different angle		4877
<input type="checkbox"/> 42	[Flood]	Unidentified flooded area, looks like a walking bridge, looks like same area as Accession 1992-30 Item 41 - just a different angle		4877
<input type="checkbox"/> 43	[Flood]	Unidentified flooded street - looks like same street as in Accession 1992-30 Item 44		4877
<input type="checkbox"/> 44	[Flood]	Unidentified flooded street - looks like same street as in Accession 1992-30 Item 43		4877
<input type="checkbox"/> 45	[Flood]	Unidentified flooded area, bridge partly under water - unidentified gentleman looking at scene, building with windows boarded up and houses in background		4877
<input type="checkbox"/> 46	William Street Sewer	Workers working on sewer, snow on the ground, train in background - Canadian Pacific, these photographs are numbered 46.1 and 46.2	1951	4877
<input type="checkbox"/> 47	[Snow Covered Area]	Unidentified snow covered area, can see buildings in the distance, could possibly be where a sewer is going in or has gone in		4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 48	[Snow Removal]	Snow removal on city street - possibly May Street, Fort William - believe former Royal Edward Hotel is in the background, these photographs are numbered 48.1, 48.2, 48.3 and 48.4 - these photos are all in the same area but are not exactly the same photo - negatives available in P010		4877
<input checked="" type="checkbox"/> 49	[Snow Removal]	Bystander watching as snow plow moves down street, negative located in P010		4877
<input type="checkbox"/> 50	[Street Scene]	Snow on street, sidewalk on west side Yonge Street looking north from Francis	[1946-1947]	4877
<input type="checkbox"/> 51	[Street Scene]	Sidewalk on west side Yonge Street looking north from Francis	Winter 1946-1947	4877
<input type="checkbox"/> 52	[Street Scene]	High snow banks from plowed street - roadway on Broadway Ave. looking south from Mary	[1946-1947]	4877
<input type="checkbox"/> 53	[Street Scene]	Roadway on Broadway Avenue looking south from Mary - high snowbanks	[1946-1947]	4877
<input type="checkbox"/> 54	[Street Scene]	Roadway on Mountain Avenue looking south from Mary - different view from Accession 1992-30 Items 55 and 56, [High snow banks - Mount McKay in background]	[1946-1947]	4877
<input type="checkbox"/> 55	[Street Scene]	Roadway on Mountain Avenue looking south from Mary - different view from Accession 1992-30 Items 54 and 56, [High snowbanks - Mount McKay in background]	[1946-1947]	4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 56	[Street Scene]	Roadway on Mountain Avenue looking south from Mary - different from Accession 1992-30 Items 54 and 55, [High snow banks - portion of Mount McKay in background]	1946-1947	4877
<input type="checkbox"/> 57	[Street Scene]	Sidewalk on Brown Street looking north from Empire, snow on sidewalk	[1946-1947]	4877
<input type="checkbox"/> 58	[Street Scene]	Roadway on Heath Street looking north from Arthur, snow on street		4877
<input type="checkbox"/> 59	[Street Scene]	Roadway on Mannion Avenue looking north from Arthur (not opened up), snow covered area	[1946-1947]	4877
<input type="checkbox"/> 60	[Street Scene]	Roadway on north side of Arthur Street looking west from Euclid Avenue - snowbanks on street - pavement clear of snow	1946-1947	4877
<input type="checkbox"/> 61	[Street Scene]	Roadway on Edward Street looking south from a point 100 feet south of Ridgeway - plow cleaning snow from street, these photographs are numbered 61.1 and 61.2	1946-1947	4877
<input type="checkbox"/> 62	[Street Scene]	James Street south of subway, snow banks - possibly portion of Mount McKay in background	[1946-1947]	4877
<input type="checkbox"/> 63	[Unidentified Street]	Unidentified road - looks like it is being graded, mountain in background	May 30, 1957	4877
<input type="checkbox"/> 64	[Unidentified Street]	Unidentified road being graded or worked on - looks like elevators in the distance	May 30, 1957	4877
<input type="checkbox"/> 65	[Unidentified Street]	Tractor or grader on an unidentified road - mountains or hills in area	June 1, 1957	4877

*Note: Negative available when checkmark in box.*

**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

<b>ITEM #</b>	<b>PHOTO TITLE</b>	<b>SUBJECT</b>	<b>DATE(S)</b>	<b>LOCATION</b>
<input type="checkbox"/> 66	[Unidentified Street]	"Burney's" taxi on an unidentified road	June 1, 1957	4877
<input type="checkbox"/> 67	[Men and Boat]	Two unidentified men kneeling in front of a boat up on blocks - trees in background	June 20, 1957	4877
<input type="checkbox"/> 68	[Construction Site]	Unidentified men working at a construction site beside a river, one man operating a crane lifting a large pipe	July 22, 1957	4877
<input type="checkbox"/> 69	[Construction Site]	Men working at an unidentified construction site - looks like a foundation		4877
<input type="checkbox"/> 70	[Dredge McKellar]	Boat on river - portion of elevators in background - sign on boat "Dredge McKellar"		4877
<input type="checkbox"/> 71	[Men in Ditch]	Three unidentified men working in a ditch - sewer or pipe in ditch		4877
<input type="checkbox"/> 72	[Broken Pipe]	Shows broken pipe, can see a portion of the back of someone kneeling		4877
<input type="checkbox"/> 73	[Sewer Construction]	Group Photo - construction workers at a construction site standing on a large sewer pipe, these photographs are numbered 73.1 and 73.2, (Chapples Limited - on envelope photo was in)		4877
<input type="checkbox"/> 74	[Sewer Line]	Shows a sewer line, (Chapples Limited - on envelope photo was in)		4877
<input type="checkbox"/> 75	[Sewer Line]	Shows work on a sewer line, hill and mountains in background, (Chapples Limited - on envelope photo was in)		4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 76	[Head Shaft of Tunnel]	Taken at head shaft of tunnel, four unidentified men standing at top		4877
<input type="checkbox"/> 77	[Head Shaft of Tunnel]	Taken at head shaft of tunnel, unidentified woman in long coat and a dog , wintertime - snow on the ground		4877
<input type="checkbox"/> 78	[Head Shaft of Tunnel]	Taken at head shaft of tunnel, two unidentified gentlemen in suits, looks like a construction area		4877
<input type="checkbox"/> 79	Forebay	Six photographs of some sort of holding tank in various stages of construction, can see mountains in some of the photographs, these photographs are numbered 79.1, 79.2, 79.3, 79.4, 79.5 and 79.6		4877
<input type="checkbox"/> 80	Forebay	Some kind of pipes		4877
<input type="checkbox"/> 81	Forebay	Tunnel being dug through rocks, tracks with carts on them into the tunnel		4877
<input type="checkbox"/> 82	Forebay	Some sort of excavation site, unidentified workmen standing in tunneled out area		4877
<input type="checkbox"/> 83	Forebay	Unidentified men standing in tunneled out area in rocks		4877
<input type="checkbox"/> 84	[Construction of Watermain Elevator D]	Construction of 18" watermain Elevator D, looks like large pipe is being loaded onto a barge		4877
<input type="checkbox"/> 85	[Construction of Watermain Elevator D]	Construction of 18" watermain Elevator D, looks like pipe is being moved by barge, houses in background along bank		4877

*Note: Negative available when checkmark in box.*



**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

<b>ITEM #</b>	<b>PHOTO TITLE</b>	<b>SUBJECT</b>	<b>DATE(S)</b>	<b>LOCATION</b>
<input type="checkbox"/> 86	[Construction of Watermain Elevator D]	Construction of 18" watermain Elevator D, looks like pipe is being moved on barge being pulled by boat called "Estelle", houses in background along bank		4877
<input type="checkbox"/> 87	[Construction of Watermain Elevator D]	Construction of 18" watermain Elevator D, looks like a pipe is being brought to shore		4877
<input type="checkbox"/> 88	Bunkhouse Used During Construction of Tunnel	Four unidentified women and three unidentified men posed outside of bunkhouse, other individuals looking out of the windows		4877
<input type="checkbox"/> 89	Bunkhouse used During Construction of Tunnel	Full view of bunkhouse, unidentified individuals looking out of windows		4877
<input type="checkbox"/> 90	[Tunnel Construction]	Taken underground during tunnel construction, three unidentified individuals in photo, two of the individuals are in Accession 1992-30 Item 91		4877
<input type="checkbox"/> 91	[Tunnel Construction]	Taken underground during tunnel construction, two unidentified individuals in photo, two of the individuals are in Accession 1992-30 Item 90		4877
<input type="checkbox"/> 92	Reservoir	Looks like early stages of construction, these photographs are numbered 92.1 and 92.2		4877
<input type="checkbox"/> 93	Reservoir	Looks like construction of reservoir, partially constructed		4877
<input type="checkbox"/> 94	Reservoir	Looks like construction closer to completion		4877
<input type="checkbox"/> 95	Reservoir	Looks like view of inside of completed reservoir		4877

*Note: Negative available when checkmark in box.*

**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

<b>ITEM #</b>	<b>PHOTO TITLE</b>	<b>SUBJECT</b>	<b>DATE(S)</b>	<b>LOCATION</b>
<input type="checkbox"/> 96	Reservoir	Looks like view of outside of completed reservoir		4877
<input type="checkbox"/> 97	Reservoir	Looks like view of outside of reservoir showing water coming out of trough		4877
<input checked="" type="checkbox"/> 98	Repairs to Reservoir	Negative located in P010, unidentified men working on reservoir		4877
<input checked="" type="checkbox"/> 99	Repairs to Reservoir	Negative located in P010, repair work		4877
<input checked="" type="checkbox"/> 100	Repairs to Reservoir	Negative located in P010, work site, unidentified men working, looks like a number of sand or cement bags piled in front of a building or shed and beside what looks like a cement mixer		4877
<input type="checkbox"/> 101	Construction of Gate Chamber [Loch Lomond]	Looks like early stages of construction, snow on the ground, one unidentified man and two women seated in construction area and one man in a lean-to or shed		4877
<input type="checkbox"/> 102	Construction of Gate Chamber [Loch Lomond]	Two unidentified women and three unidentified men posed in front of a large pipe and seated on some sort of logs or posts		4877
<input type="checkbox"/> 103	Construction of Gate Chamber [Loch Lomond]	Looks like early stages of construction, snow on the ground, individuals working in area		4877
<input type="checkbox"/> 104	Construction of Gate Chamber [Loch Lomond]	Looks like early stages of construction, three men and four women standing under structure and around some sort of well or pulley		4877
<input type="checkbox"/> 105	Construction of Gate Chamber [Loch Lomond]	Men on scaffolding putting up stone walls		4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 106	Construction of Gate Chamber [Loch Lomond]	View taken from out in water, stone "Gate Chamber" being constructed on shore and some type of breakwater being constructed out into the water		4877
<input type="checkbox"/> 107	Construction of Gate Chamber	Stone "Gate Chamber" nearing completion, looks like a turret on a castle, on back of photo "Gatehouse at Loch Lomond"		4877
<input type="checkbox"/> 108	Construction of Gate Chamber [Loch Lomond]	Photo of entrance to stone "Gate Chamber", wooden door with fancy steel hinges extending across the wood		4877
<input type="checkbox"/> 109	Construction of Gate Chamber [Loch Lomond]	Looks like an opening ceremony at the stone "Gate Chamber", numerous people standing about, one gentleman with top hat possibly making a speech		4877
<input type="checkbox"/> 110	Construction of Gate Chamber [Loch Lomond]	Looks like an opening ceremony, numerous people standing about on shore near the stone "Gate Chamber", a number of horse drawn carriages are on the shore, four or five individuals in a small boat going across the water		4877
<input type="checkbox"/> 111	Construction of Gate Chamber [Loch Lomond]	The stone "Gate Chamber" from the water - two men standing close to the end of the breakwater or pathway out in water		4877
<input type="checkbox"/> 112	Construction of Gate Chamber [Loch Lomond]	View of stone "Gate Chamber" taken from breakwater or pathway into the water		4877
<input type="checkbox"/> 113	18" Stave Pipe Line	View of pipe in ditch		4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 114	Old Screen Chamber	Looking down on two men in a heavily treed area - possibly Mount McKay, one man looking through some type of camera		4877
<input type="checkbox"/> 115	Old Screen Chamber	Forebay showing spillway		4877
<input type="checkbox"/> 116	Old Screen Chamber	Similar to Accession 1992-30 Item 115 - Forebay showing spillway, unidentified individual standing beside spillway and a shed of some sort up on hill		4877
<input type="checkbox"/> 117	Old Screen Chamber	Construction work - wooden forms have been constructed		4877
<input type="checkbox"/> 118	Old Screen Chamber	Unidentified man standing beside concrete structure		4877
<input type="checkbox"/> 119	Old Screen Chamber	Old screen chamber		4877
<input checked="" type="checkbox"/> 120	Construction of New Screen Chamber Forebay	Negative located in P010	1940	4877
<input checked="" type="checkbox"/> 121	Construction of New Screen Chamber Forebay	Negative located in P010, new screen chamber mat on base, five unidentified workmen in photo	Oct. 6, 1940	4877
<input checked="" type="checkbox"/> 122	Construction of New Screen Chamber Forebay	Negative located in P010, pouring concrete mat on base for new screen chamber Forebay, four unidentified workmen in photo	Oct. 6, 1940	4877
<input checked="" type="checkbox"/> 123	Construction of New Screen Chamber Forebay	Negative located in P010, material and mixer set up for concrete work new screen chamber Forebay, three unidentified workmen in photo	Oct. 6, 1940	4877
<input checked="" type="checkbox"/> 124	Construction of New Screen Chamber Forebay	Negative located in P010, showing 18" and 24" pipe lines at point where new screen chamber pipe lines will connect	Oct. 9, 1940	4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 125	Construction of New Screen Chamber Forebay	Negative located in P010, similar to Accession 1992-30 Item 126, new screen chamber Forebay showing 18" and 24" pipe line connections, unidentified workers in photo	Oct. 9, 1940	4877
<input checked="" type="checkbox"/> 126	Construction of New Screen Chamber Forebay	Negative located in P010, new screen chamber Forebay showing one 18" and two 24" pipes ready for x connecting to 18" and 24" supply lines and one 24" spare for future, unidentified workers in photo	Oct. 9, 1940	4877
<input checked="" type="checkbox"/> 127	Construction of New Screen Chamber Forebay	Negative located in P010, showing bags of cement and mixer	Oct. 9, 1940	4877
<input checked="" type="checkbox"/> 128	Construction of New Screen Chamber(Forebay) on Envelope the photo was in	Negative located in P010. New screen chamber Forebay showing forming & 36" Cast Iron Spillway Pipe	October 9, 1940	4877
<input checked="" type="checkbox"/> 129	Construction of New Screen Chamber(Forebay) on Envelope the photo was in	Negative located in P010. Showing 18" x 24" Y at supply line foot of Forebay	October 10, 1940	4877
<input checked="" type="checkbox"/> 130	Construction of New Screen Chamber(Forebay) on Envelope the photo was in	Negative located in P010. Showing concrete structure		4877
<input checked="" type="checkbox"/> 131	McQuaig Lake (Re: Water Pollution)on envelope the photo was in	Negative located in P010. McQuaig Lake on back of photo. Winter, snow covered-4 sled horses right hand side of photo		4877
<input checked="" type="checkbox"/> 132	McQuaig Lake (Re: Water Pollution)on envelope the photo was in	Negative located in P010. Campbell's Cook Camp-Near McQuaig Lake, winter, ground is snow covered		4877
<input checked="" type="checkbox"/> 133	McQuaig Lake (Re: Water Pollution)on envelope the photo was in	Negative located in P010. Campbell's Sleeping Camp-Near McQuaig Lake, winter, ground is snow covered		4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 134	McQuaig Lake (Re: Water Pollution)on envelope the photo was in	Negative located in P010. Campbell's stable near McQuaig Lake. Four unidentified men standing outside of stable. Winter, ground is snow covered.		4877
<input checked="" type="checkbox"/> 135	McQuaig Lake (Re: Water Pollution)on envelope the photo was in	Negative located in P010. Two unidentified men outside of rough looking buildings, one of the buildings could possibly be Campbell's sleeping Camp-See item 133		4877
<input type="checkbox"/> 136	McQuaig Lake (Re: Water Pollution)on envelope the photo was in	Four men backs to camera pickaxing and digging, winter, ground is snow covered		4877
<input type="checkbox"/> 137	McQuaig Lake (Re: Water Pollution)on envelope the photo was in	Six men backs to camera pickaxing and digging, winter, ground is snow covered		4877
<input checked="" type="checkbox"/> 138	Kam River Xing -G.T.P. Bridge	Negative located in P010. Kam River Xing downstream main G.T.P. Bridge removing sleeve from under water position to pt. above water	May 15, 1942	4877
<input checked="" type="checkbox"/> 139	Partially Constructed Structure	Negative located in P010. Two unidentified workers in small partially constructed structure. Large pipes on either side of building and looks like one going through structure as well. On envelope photo was in "Chlorination Bldg"		4877
<input checked="" type="checkbox"/> 140	Partially Constructed Structure	Negative located in P010. Two unidentified workers in small partially constructed structure. Large pipes on either side of building and looks like one going through structure as well. On envelope photo was in "Chlorination Bldg"		4877

*Note: Negative available when checkmark in box.*

**Accession # 1992-30**                      **Dept./ Division: Public Works**  
**Series 130 Thunder Bay Sewer & Water Photograph Collection**                      **A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 141	Pipes in Ditch	Negative located in P010. Three pipes in some sort of ditch-on envelope photo was in "Chlorination Bldg."		4877
<input checked="" type="checkbox"/> 142	Tractor Operator	Negative located in P010. Tractor operator bringing up a large broken pipe from the ground.		4877
<input type="checkbox"/> 143	Large Pipe	View of large pipe running along a ditch for a long distance.	January 13, 1955	4877
<input checked="" type="checkbox"/> 144	Roadway Along Bush	Negative located in P010. View of rough looking roadway along bush		4877
<input checked="" type="checkbox"/> 148	Steel Pipe Ramp	Negative located in P010. Steel pipe ramp 90'+ removed from island bank. No record of such shown on plans of crossing(On back of Photo)	November 1, 1962	4877
<input checked="" type="checkbox"/> 149	Mission Crossing	Negative located in P010. Downstream line Mission Crossing new materials to replace old line. Train & Ship in background	November 1, 1962	4877
<input checked="" type="checkbox"/> 150	Mission Crossing	Negative located in P010. Downstream line Mission Crossing, looks like old pipes & Material	November 1, 1962	4877
<input checked="" type="checkbox"/> 151	Mission Crossing	Negative located in P010. Downstream line Mission Crossing, looks like old pipes, looks like a pile of wood chips In the background, train and ship in the background as well	November 1, 1962	4877
<input type="checkbox"/> 154	Fort William Airport	Break-plowing & loading stumps & roots Fort William Airport	September 20, 1938	4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 155	Fort William Airport	Break-Plowing Fort William Pigeon Timber Co. Contractor	September 20, 1938	4877
<input type="checkbox"/> 156	Fort William Airport	Clearing & Burning operations Fort William Airport	September 20, 1938	4877
<input type="checkbox"/> 157	Fort William Airport	1 of 2 piles of stumps piled ready for burning, Fort William Airport	September 20, 1938	4877
<input type="checkbox"/> 158	Fort William Airport	12 x 28 twin laminex 680' long- Unidentified man looks like he is inserting a crowbar into the sides of the "Laminex" some sort of ditch constructed out of wood	c.1939	4877
<input type="checkbox"/> 159	Fort William Airport	Twin Laminex 12 x 28 680' long-Different view of same type of wooden ditch like structure in item #158	c.1939	4877
<input type="checkbox"/> 160	Fort William Airport	View of Twin Laminex from inside catch basin	c.1939	4877
<input type="checkbox"/> 161	Fort William Airport	Laminex 15" x 36" 200' long- Some type of wooden ditch like structure-two unidentified men are putting on wooden top.	c.1939	4877
<input type="checkbox"/> 162	Fort William Airport	Ditch with water in it, possibly something to do with "Laminex" at Fort William Airport mentioned in items 158-161, wooden forms in piles along ditch	c.1938	4877
<input type="checkbox"/> 163	Fort William Airport	Ditch with water in it, possibly something to do with "Laminex" at Fort William Airport mentioned in items 158-161, rocks along shoulders of ditch, wooden forms in piles along ditch	c.1938	4877

*Note: Negative available when checkmark in box.*



<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 164	Fort William Airport	Ditch with water in it, possibly something to do with "Laminex" at Fort William Airport mentioned in items 158-161	c.1938	4877
<input type="checkbox"/> 165	Fort William Airport	Ditch with water in it, possibly something to do with "Laminex" at Fort William Airport mentioned in items 158-161, looks like wooden forms being constructed for ditch	c.1938	4877
<input type="checkbox"/> 166	Fort William Airport	Ditch with water in it, possibly something to do with "Laminex" at Fort William Airport mentioned in items 158-161, looks like wooden forms being constructed for ditch, wooden forms in piles along ditch.	c.1938	4877
<input type="checkbox"/> 167	Fort William Airport	Possibly something to do with "Laminex" at Fort William Airport mentioned in items 158-161, workmen in ditch and wooden forms being constructed for ditch, wooden forms in piles along ditch.		4877
<input type="checkbox"/> 168	Airfield	possibly an Airfield	September 3, 1938	4877
<input type="checkbox"/> 169	Airfield	Possibly an Airfield	September 3, 1938	4877
<input type="checkbox"/> 170	Sioux Lookout Airport	X-Section of ditching N.W. runway Sioux Lookout Airport, also boundary lights spacing	September 3, 1938	4877
<input type="checkbox"/> 171	Sioux Lookout Airport	N.W. Runway showing boundary light and grass catch	September 3, 1938	4877
<input type="checkbox"/> 172	Sioux Lookout Airport	Power Ho Beacon light and meteorological station	September 3, 1938	4877
<input type="checkbox"/> 173	Sioux Lookout Airport	Catch basin and 36" X drain on N.W. runway	September 3, 1938	4877

*Note: Negative available when checkmark in box.*

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 174	Small Planes	Negative located in P010. Small planes and various buildings-Looks like the same place as in item 175,176,179		4877
<input checked="" type="checkbox"/> 175	Small Planes	Negative located in P010. Small Planes and what could be a hangar, also a vehicle-Looks like the same place as in item 174,176		4877
<input checked="" type="checkbox"/> 176	Small Planes, Building & Parked Vehicles	Negative located in P010. Two small planes, buildings and parked vehicles-could be same place as items 174,175		4877
<input checked="" type="checkbox"/> 177	Small Planes	Negative located in P010. Small Plane-"CF-BMV" in large letters on plane		4877
<input type="checkbox"/> 178	Small Plane	Small plane, building and vehicle in background		4877
<input type="checkbox"/> 179	Small Planes, Vehicles, Building & People	Two small planes, 2 vehicles, building and a few unidentified people-looks like same place as item 174		4877
<input type="checkbox"/> 180	Cattle Pass	The following is typed on a sheet tissue like paper attached to the front of the photo: Reinforced concrete cattle pass of expensive design being removed by blasting from old road after new highway constructed a few hundred yards away. The cattle pass in the new highway was constructed of laminex at considerably less cost if further diversion should ever occur the laminex may be removed and reinstalled without this high cost obsolescence.	July 1939	4877

*Note: Negative available when checkmark in box.*

Accession # 1992-30

Dept./ Division: Public Works

Series 130 Thunder Bay Sewer & Water Photograph Collection

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 181	Scott International Highway	Scott International Highway near Fort William galvanized corrugated iron pipe and concrete being replaced by Northern Wood stave pipe due to rust in one case, frost and ___? In the other-Unidentified man and vehicle standing on side of road.	August 24, 1939	4877
<input type="checkbox"/> 182	International Highway	International Highway near Fort William-looks like pipes as in item 181	August 24, 1939	4877
<input checked="" type="checkbox"/> 183	Broken Pipe	Negative located in P010. Broken Pipe in new 24" line near City Road, Indian House	November 17, 1957	4877
<input checked="" type="checkbox"/> 184	Tunnel Crossing	Negative located in P010. Tunnel Crossing, river or lake, Elevators on far side		4877
<input checked="" type="checkbox"/> 185	Downstream Line	Negative located in P010. 18" downstream line connection between old and new		4877
<input checked="" type="checkbox"/> 186	New Valve Chamber	Negative located in P010. New Valve Chamber 24" x 18" altitude valves -unidentified man in photo as well	June 19, 1958	4877
<input checked="" type="checkbox"/> 187	Robin's Nest	Negative located in P010. Robin's Nest in drag line boom-Reservoir	June 1958	4877
<input checked="" type="checkbox"/> 196	Ships Docked	Negative located in P010. Two ships docked-elevators and train in background		4877

Note: Negative available when checkmark in box.

**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

<b>ITEM #</b>	<b>PHOTO TITLE</b>	<b>SUBJECT</b>	<b>DATE(S)</b>	<b>LOCATION</b>
<input checked="" type="checkbox"/> 197	Morgan Avenue Ditch from Arthur Street	Negative located in P010. Morgan Avenue Ditch from Arthur Street. Ditch with water in it, a building on the left and in the distance, also mountains in the background. Hydro or telephone pole on right and a portion of a fence-photo almost the same as item #198	August 3, 1939	4877
<input checked="" type="checkbox"/> 198	Morgan Avenue Ditch from Arthur St.	Negative located in P010. Morgan Ave. ditch from Arthur St., 15 min. downpour-photo almost the same as item #197	August 3, 1939	4877
<input checked="" type="checkbox"/> 199	Ditch North side of Rundway	Negative located in P010. Ditch north side of No. 1 runway from east end of runway-ditch filled with water	August 3, 1939	4877
<input checked="" type="checkbox"/> 200	Across No. 1 Runway from East End of Runway	Negative located in P010. Across No. 1 runway from east end of runway-land looks flooded and it looks like there are farm buildings in the background	August 3, 1939	4877
<input checked="" type="checkbox"/> 201	East End of No. 1 runway from S/S of Runway	Negative located in P010. East end of No. 1 runway from S/S of Runway-ditch filled with water on right hand side and some water on land as well	August 3, 1939	4877
<input checked="" type="checkbox"/> 202	Across No. 1 Runway from S/S of Runway	Negative located in P010. Across No. 1 runway from S/S of runway along Morgan Ave. ditch. Ditch filled with water and land flooded.		4877
<input checked="" type="checkbox"/> 203	Across No. 1 Runway from N/S of Runway	Negative located in P010. Across No. 1 runway from N/S of runway-flooded land, mountains in background	August 3, 1939	4877

*Note: Negative available when checkmark in box.*

**Accession # 1992-30**                      **Dept./ Division: Public Works**  
**Series 130 Thunder Bay Sewer & Water Photograph Collection**                      **A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 204	Across East End of No. 1 Down No. 3 Runway	Negative located in P010. Across east end of No. 1 down No. 3 Runway-Flooded land, dark sky, hills or mountains in backgrounds	August 3, 1939	4877
<input checked="" type="checkbox"/> 205	Pipe Lowered in Water	Negative located in P010. Pipe being lowered into water		4877
<input checked="" type="checkbox"/> 206	Lowering Section 3-Col"	Negative located in P010. On back of photo "Lowering Section 3-Col"-some kind of pipe is being lowered into the water, three chains are holding it but can't see what they are connected to. Two men watching, possibly on a boat and a small boat is docked		4877
<input checked="" type="checkbox"/> 207	Barge 3-Col"	Negative located in P010. On back of photo "Barge 3 Col" - Looks like large pipes loaded on a barge, Two unidentified men on the barge-Almost the same photo as item #208		4877
<input checked="" type="checkbox"/> 208	Large Pipes loaded on a Barge	Negative located in P010. Looks like large pipes loaded on a barge-Two unidentified men on the barge. Almost the same photo as Item #207		4877
<input checked="" type="checkbox"/> 209	Overhead Loader or Crane	Negative located in P010. Some type of overhead loader or crane. Also a barge or boat with "Thunder Bay Harbor Improvements Ltd." on the side- Piles of what could be ore- photo similar to item #210		4877

*Note: Negative available when checkmark in box.*

**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 210	Overhead Loader or Crane	Negative located in P010. Some type of overhead loader or crane. Also a barge or boat with "Thunder Bay Harbor Improvements Ltd." on the side- Piles of what could be ore- Mountains in the background, possibly Mt. McKay - photo similar to item #209.		4877
<input checked="" type="checkbox"/> 211	Large Pipes on Ground	Negative located in P010. Large pipes on the snow covered ground-tractor hauling pipe-unidentified workers		4877
<input checked="" type="checkbox"/> 212	Reservoir	Negative located in P010. Looks like inside of reservoir	May 24, 1955	4877
<input checked="" type="checkbox"/> 213	Watermain Pipes	Negative located in P010. Possibly watermain pipes-triangular coverings over same and small building at back		4877
<input checked="" type="checkbox"/> 214	24" Line Looking Towards Reservoir	Negative located in P010. New 24" line looking towards Reservoir-Four unidentified workmen in photo	January 13, 1955	4877
<input checked="" type="checkbox"/> 215	Fort William Watermain	Negative located in P010. Pipes being lowered into ditch by crane and workers are assisting		4877
<input type="checkbox"/> 216	Deterioration of Walls	Showing deterioration of walls [possibly in reservoir]	May 24, 1955	4877
<input checked="" type="checkbox"/> 217	Pipe Line	Negative located in P010. Looking east along pipe line, boulders in distance - some sort of tractor unit in photo	March 9, 1955	4877
<input checked="" type="checkbox"/> 218	Fort William Watermain	Negative located in P010. Snow on ground-cleared area, individual on snowmobile, mountains in the distance		4877

*Note: Negative available when checkmark in box.*

**Accession # 1992-30****Dept./ Division: Public Works****Series 130 Thunder Bay Sewer & Water Photograph Collection****A**

<b>ITEM #</b>	<b>PHOTO TITLE</b>	<b>SUBJECT</b>	<b>DATE(S)</b>	<b>LOCATION</b>
<input type="checkbox"/> 219	Fort William Waterworks	Fort William Waterworks - Forebay 1965-Screen Chamber	1965	4877
<input type="checkbox"/> 220	Fort William Waterworks	Fort William Waterworks Forebay 1965- Screen Chamber	1965	4877
<input type="checkbox"/> 221	Fort William Waterworks	Fort William Waterworks Forebay 1965- Screen Chamber	1965	4877
<input type="checkbox"/> 222	Fort William Waterworks	Fort William Waterworks Forebay 1965- Screen Chamber	1965	4877
<input type="checkbox"/> 223	Harbor Patrol Boat	Small boat with "Harbor Patrol" on top in River or lake-houses in background		4877
<input checked="" type="checkbox"/> 224	Kam River	Negative located in P010. On envelope photo was in: Location from which pipe was stolen, North bank Kam River	September 14, 1957	4877
<input checked="" type="checkbox"/> 226	Men Working	Negative located in P010. Men working on sewer on city street-sign on house at corner "Franklin St. S.". Looks like it is at the corner of Franklin and Arthur St. Fort William. Looks like city telephone building in distance-Mathews Sash and Door across street (Arthur)	August 23, 1956	4877
<input checked="" type="checkbox"/> 227	Man Working	Negative located in P010. Individual working in sewer where fire hydrant is. Most likely at the corner of Franklin and Arthur St., Fort William-As in item #226	August 23, 1956	4877
<input checked="" type="checkbox"/> 229	River Crossing	Negative located in P010. River Crossing-on envelope photo was in. On back of photo-Jack _____ & Dick waiting for traffic to clear. Three men on a dock, boat or barge-one in some type of diving equipment	August 20, 1954	4877

*Note: Negative available when checkmark in box.*

Accession # 1992-30

Dept./ Division: Public Works

Series 130 Thunder Bay Sewer & Water Photograph Collection

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 230	Main River Crossing	Negative located in P010. 18" Main River crossing-Three men on a dock, boat or barge one in some type of diving equipment. Can see a holding tank on the other side of the river	August 20, 1954	4877
<input checked="" type="checkbox"/> 231	Marconi Aboard Repair Scow	Negative located in P010. Marconi aboard repair scow-can see six men on board scow-one operating some type of radio equipment and one man in diving equipment. River crossing-on envelope photo was in	August 20, 1954	4877
<input checked="" type="checkbox"/> 232	Six Men on Board Scow	Negative located in P010. Six men on board scow - River crossing-on envelope photo was in	[August 20, 1954]	4877
<input checked="" type="checkbox"/> 233	Man in Diving Equipment	Negative located in P010. Man in the diving equipment being lowered into the water (4 other men in the photo as well) River crossing -on envelope photo was in	[August 20, 1954]	4877
<input checked="" type="checkbox"/> 234	Men on Scow or Barge	Negative located in P010. Group of 10 men on the Scow or Barge-One man is in the diving suit-Behind the men is a large ship "Bricoldoc" River crossing-on envelope photo was in	[August 20, 1954]	4877
<input checked="" type="checkbox"/> 235	Men on Barge or Scow	Negative located in P010. A few men on board the barge or scow-one man in a suit. River crossing-on envelope photo was in	[August 20, 1954]	4877
<input checked="" type="checkbox"/> 236	Unidentified Individual	Negative located in P010. Unidentified individual looking at some kind of forms covering a pipe	October 3, 1958	4877

Note: Negative available when checkmark in box.



<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 237	Type of Forms	Negative located in P010. Close up of some type of forms	October 3, 1958	4877
<input checked="" type="checkbox"/> 238	Reservoir	Negative located in P010. Unidentified individual walking along top of wall some type of crane is in the background		4877
<input checked="" type="checkbox"/> 239	Reservoir	Negative located in P010. Pipe going through cement-looks like work is being done on it.		4877
<input checked="" type="checkbox"/> 240	Reservoir	Negative located in P010. Unidentified individual standing on top of wall-portion of his face is cut off		4877
<input type="checkbox"/> 241	Wall	Photo of wall possibly showing signs of deterioration		4877
<input checked="" type="checkbox"/> 242	Man beside a Truck	Negative located in P010. Unidentified man standing beside a truck	July 20, 1956	4877
<input checked="" type="checkbox"/> 243	Strappings on Ground	Negative located in P010. Some sort of strappings on ground and piled lumber	July 20, 1956	4877
<input checked="" type="checkbox"/> 244	Large Pipe	Negative located in P010. Some type of large pipe made of wood	July 20, 1956	4877
<input checked="" type="checkbox"/> 245	Truck with Crane	Negative located in P010. Something either being lifted out or put into the box of a truck by a crane- can see elevators in the background	July 20, 1956	4877

*Note: Negative available when checkmark in box.*

Accession # 1992-30

Dept./ Division: Public Works

Series 130 Thunder Bay Sewer & Water Photograph Collection

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 246	[Street Scene-Vickers St]	Negative located in P010. In front of Snelgrove-Evans Fuel, which according to Henderson's Directory was located at 125 S. Vickers in the 1920's & 111 S. Vickers from Approx. 1929-1950 and then on Syndicate Ave. Can see train cars & some sort of unloading devices & Snelgrove Evans Truck. Can see C.N. Building in background which was also on Vickers St.. Almost the same photo as item 24		4877
<input checked="" type="checkbox"/> 247	[Street Scene-Vickers St]	Negative located in P010. In front of Snelgrove-Evans Fuel, which according to Henderson's Directory was located at 125 S. Vickers in the 1920's & 111 S. Vickers from Approx. 1929-1950 and then on Syndicate Ave. Can see train cars & some sort of unloading devices & Snelgrove Evans Truck. Can see C.N. Building in background which was also on Vickers St. Almost the same photo as item #246		4877
<input checked="" type="checkbox"/> 248	[Street Scene-Vickers St]	Negative located in P010. Showing Street-can see Snelgrove-Evans Fuel and other buildings. Snelgrove-Evans according to Henderson's Directory was at 125 S. Vickers in the 1920's and 111 S. Vickers for approx. 1929-1950 & then on Syndicate Ave.		4877

Note: Negative available when checkmark in box.

<b>Accession #</b> 1992-30	<b>Dept./ Division:</b> Public Works
<b>Series</b> 130 Thunder Bay Sewer & Water Photograph Collection	<b>A</b>

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 249	[Steet Scene-Vickers St.]	Negative located in P010. In front of Snelgrove-Evans Fuel, which according to Henderson's Directory was at 125 S. Vickers in the 1920's and 111 S. Vickers from approx. 1929-1950 & then on Syndicate Ave. Looks like train cars are filled with coal-Worker standing on back of truck and two others wokring as well.		4877
<input checked="" type="checkbox"/> 250	[Street Scene-Vickers St.]	Negative located in P010. Street scene [Vickers St.] In front of Snelgrove-Evans Fuel, which according to Henderson's Directory was at 125 S. Vickers in the 1920's and 111 S. Vickers from approx. 1929-1950 & then on Syndicate Ave. Looks like train cars are filled with coal-Men working looks like they are loading rail cars-can see C.N. Building in background which was also on Vickers St.		4877
<input checked="" type="checkbox"/> 252	[Street Scene-Vickers St.]	Negative located in P010. Showing train tracks and rail cars and Canadian National Building in background (was located on N. Vickers St.)		4877
<input checked="" type="checkbox"/> 253	Unidentified House	Negative located in P010. Unidentified House on Vickers St. believe it is house beside Snelgrove-Evans Fuels-see items 250 & 251		4877
<input checked="" type="checkbox"/> 254	New 24" Line Reservoir	Negative located in P010. Can see part of a person working in construction area-looks like supports have been put up		4877
<input checked="" type="checkbox"/> 255	Fractured Valve	Negative located in P010. Photo of above-unidentified building in background		4877

*Note: Negative available when checkmark in box.*