

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 1	Hazelwood Dam	Photo of Dam	[1914]	P005
<input type="checkbox"/> 2	Hazelwood Dam	Bottom portion of person standing on top of Dam	[1914]	P005
<input type="checkbox"/> 3	Hazelwood Dam	Two unidentified gentlemen standing in front of Dam	[1914]	P005
<input type="checkbox"/> 4	Hazelwood Dam	Unidentified gentleman seated in front of wall and portion of another individual sitting on top of Dam	[1914]	P005
<input type="checkbox"/> 5	Hazelwood Dam	Two unidentified gentlemen holding their arms up against wall of Dam	[1914]	P005
<input type="checkbox"/> 6	Electric Two Passenger Car	Two unidentified women seated in a car	[1914]	P005
<input type="checkbox"/> 7	Manitoba Telephone Building - Portage La Prairie, Manitoba	Photo of Manitoba Telephone Building - Portage La Prairie, Manitoba		P015
<input type="checkbox"/> 8	The MacDonald Electric Thawing Apparatus	The MacDonald Electric Thawing Apparatus - patented July 22, 1919 for the Corporation of Ottawa - Unidentified individual seated at front and pulled by horse and on sled	[1920-1921]	P005
<input type="checkbox"/> 9	Gears	Gears - marked 1, 2 & 3 These photographs are numbered 9.1, 9.2 & 9.3. All 3 scanned photographs available.	[1923]	P005
<input type="checkbox"/> 10	Ward W D Model	Ward W D Model Load Capacity 6455 to 7355 lbs. (Including Body) - #305 on Photo		P015
<input type="checkbox"/> 11	WD 2 Chassis	#341 on photo		P015
<input type="checkbox"/> 12	Mirror Candy Co. Vehicle	Photo of vehicle - #365 on photo		P015

Note: Negative available when checkmark in box.

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 13	Ward W A Model	Load Capacity 2534 to 3250 lbs. (Including Body) - #388 on photo		P015
<input type="checkbox"/> 14	Chassis	#391 on photo		P015
<input type="checkbox"/> 15	W H Chassis 3/4 Front View	#445 on photo		P015
<input type="checkbox"/> 16	Bakery Vehicles	Approximately ten vehicles parked in front of Bakery - Welle Boether Bakery on vehicles - On back of photo - American Baking, St. Louis, Mo.		P015
<input type="checkbox"/> 17	Bakery Truck (Welle Boettler Bakery)	WB 2 - Truck - unidentified individual in truck in front of bakery - #454 on photo - On back of photo - American Bakery Co., St. Louis, Mo.	[1922-1923]	P015
<input type="checkbox"/> 18	California Laundry Vehicle, Hollywood, California	Two unidentified men - one seated in and one standing on vehicle	[1922]	P015
<input type="checkbox"/> 19	National Laundry Vehicles	#487 on photo - National Family Laundry Service Corp., New York City, W A Model - load capacity 2534 to 3250 lbs. (Including Body)		P015
<input type="checkbox"/> 20	Bowe - Perry Pies Vehicle, St. Louis, Mo.	Photo of vehicle - #559 on photo	[1923]	P015
<input type="checkbox"/> 21	Hydro Sub-Station, Ottawa St., Hamilton	Photo of above - Bernard H. Prack, Architect		P005
<input type="checkbox"/> 22	Hydro Sub-Station, Ottawa St., Hamilton	Inside view of above - Bernard H. Prack, Architect		P005
<input type="checkbox"/> 23	Hydro Sub-Station and Garage, Hughson St., Hamilton	Photo of drawing of sub-station, Bernard H. Prack, Architect		P005
<input type="checkbox"/> 24	Hydro Sub-Station and Garage, Hughson St., Hamilton	Photo of drawing of sub-station - looks like different view from Item 23, Bernard H. Prack, Architect		P005

Note: Negative available when checkmark in box.

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 25	Bell Telephone Co. Vehicle	Side view of vehicle - 357 maximum load		P015
<input type="checkbox"/> 26	Bell Telephone Co. Vehicle	Rear view of vehicle		P015
<input type="checkbox"/> 27	66,000 Volt Assembly & Details of Contacts	#8431 on photo		P015
<input type="checkbox"/> 28	66,000 Volt Assembly & Details of Contacts	#8374 on photo - enlarged photo of one section		P015
<input type="checkbox"/> 29	Outdoor GA-3 Breaker	#8230 (Drawing)		P015
<input type="checkbox"/> 30	Ch-2 Breaker	#8101		P015
<input type="checkbox"/> 31	Octagonal Bronze Lantern	Taken on Sunnyside Boulevard, Toronto - daytime		P015
<input type="checkbox"/> 32	Octagonal Bronze Lantern	Taken on Sunnyside Boulevard, Toronto - nighttime		P015
<input type="checkbox"/> 33	Octagonal Bronze Lantern	Taken on Oak St. in the River Heights Residential District in Winnipeg - daytime		P015
<input type="checkbox"/> 34	Octagonal Bronze Lantern	Taken on Oak St. in the River Heights Residential District in Winnipeg - #8992-4 Foote - on photo		P015
<input type="checkbox"/> 35	Leyland Lioness Motor Bus	#3930 on photo, sign on bus "Sunnyhurst" On back of photo - passenger 26 seater (Lioness - PLCI)		P015
<input type="checkbox"/> 36	REO Truck	#6134 - REO six cylinder, one and a half ton truck		P015
<input type="checkbox"/> 37	Interurban Passenger Car #13	Rail Car - Mesaba Railway Co. 13 - on side of car		P005
<input type="checkbox"/> 38	Interurban Passenger Car #18	Rail Car - Mesaba Railway 18 on side of car		P005
<input type="checkbox"/> 39	City Passenger Car #33	Rail Car - Mesaba Railway Co. 13 on side of car		P005

Note: Negative available when checkmark in box.

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 40	Express Car #101	Rail car - Mesaba Railway Co. 101 - on side of car		P005
<input type="checkbox"/> 41	Snow Plow #99	Rail car		P005
<input type="checkbox"/> 42	Tree Trunks	Four photos of tree trunks and branches indicating sources of radio interference - photos numbered 42.1, 42.2, 42.3 and 42.4. All 4 scanned photographs available.		P005
<input type="checkbox"/> 43	Hydro Dam Calendar	Photo of dam with calendar below it for the month of January 1927. Below dam is the wording "The Power Behind the Home". Below calendar is the wording "The Municipal Hydro Electric System". Sketches of various household electric devices surround the dam and calendar.	Jan. 1927	P005
<input type="checkbox"/> 44	Street Car Advertising	Advertising on roof		P005
<input type="checkbox"/> 45	Alabaster Globe Light Fixture			P015
<input type="checkbox"/> 46	[Rail Car]	Single truck, double end, one man car, built by Cincinnati Car Co.		P005
<input type="checkbox"/> 47	[Rail Car]	Double truck, double end, one man car built by Taylor Electric Co.		P005
<input type="checkbox"/> 48	Signal Equipment	Photos are numbered 48.1 and 48.2. Both scanned photographs available.		P005
<input type="checkbox"/> 49	Switching Equipment	P-3967 metal clad switching equipment		4861
<input type="checkbox"/> 50	Current River Dam	Men working on dam	Sep. 9, 1932	P005
<input type="checkbox"/> 51	Current River Dam	Men working on dam	Sep. 9, 1932	P005

Note: Negative available when checkmark in box.

Accession # 1993-01 **Dept./ Division: Public Works**

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 52	Current River Dam	Wall in need of repair	Sep. 9, 1932	P005
<input type="checkbox"/> 53	Street Scene Showing Street Lamp	Street Scene - vehicle in photo has a British Columbia Licence Plate	1929	P015
<input type="checkbox"/> 54	Lamp Fixture			P015
<input type="checkbox"/> 55	Radio Transmitter MD-1233	Power amplifier and modulator unit, oscillator and frequency doubling unit, power control unit		P015
<input type="checkbox"/> 56	Transmitter MD1233	Rear elevation		P015
<input type="checkbox"/> 57	Transmitter MD-1233	Left side elevation		P015
<input type="checkbox"/> 58	Power Amplifier & Modulator Unit	Right side elevation		P015
<input type="checkbox"/> 59	Power Amplifier & Modulator Unit	Left side elevation		P015
<input type="checkbox"/> 60	Oscillator and Frequency Doubling Unit (Plan)			P015
<input type="checkbox"/> 61	Power Control Unit (Plan)			P015
<input type="checkbox"/> 62	Distribution Type Transformer	Distribution type transformer showing mounting of tap changing switch and arrangement of high voltage and low voltage removable bushings and also lugs of primary and secondary leads permitting removal of transformer from tank without damaging leads		P028
<input type="checkbox"/> 63	Rhombic Glassware	Photos are numbered 63.1, 63.2 and 63.3. All 3 scanned photographs available.		P005
<input type="checkbox"/> 64	Wall "Neophone" Telephone			P015
<input type="checkbox"/> 65	Scene of Accident - Pine & Van Norman Streets	Looking north on Pine Street	Dec. 17, 1932	P015

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 66	Scene of Accident - Pine & Van Norman Streets	Looking up Van Norman Street	Dec. 17, 1932	P015
<input type="checkbox"/> 67	Scene of Accident - Pine & Van Norman Streets	Looking east down Van Norman Street	Dec. 17, 1932	P015
<input type="checkbox"/> 68	Street Lighting Fixture	Street scene showing ornamental street lighting fixture for pole mounting		P005
<input type="checkbox"/> 69	Occasional Glass Table Lamps			P005
<input type="checkbox"/> 70	Occasional Glass Table Lamps			P005
<input type="checkbox"/> 71	Nachod Automatic Headway Recorder			P005
<input type="checkbox"/> 72	Leyland Bus	B-137 CC & F Co. Ltd. Montreal Works - Mar. 1932 - BO-22-29 passenger bus body mounted on Leyland chassis - built for Sherbrooke City Transit Company	Mar. 1932	P015
<input type="checkbox"/> 73	[Light Fixture]	#6830 special cast iron bracket and form 12 luminaire with 118-1118 alabaster rippled glassware		P015
<input type="checkbox"/> 74	The T. Eaton Co. Ltd., College Street Store, Toronto, Ontario	Floodlighting of the T. Eaton Co. Ltd., College Street Store, Toronto, Ontario		P015
<input type="checkbox"/> 75	[Lighting Fixture]	Form 12 novalum unit N fitter with 118-1118 light or medium alabaster rippled glassware		P015
<input type="checkbox"/> 76	Lighting Fixture	Special cast iron bracket and form 12 luminaire with 118-1118 alabaster rippled glassware supplied to Port Arthur Utilities Commission		P015
<input type="checkbox"/> 77	Toy Car	Pullmobile		P005

Note: Negative available when checkmark in box.

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 78	Advertising on Street Cars	Illumination of front of street cars for advertising purposes		P005
<input type="checkbox"/> 79	Port Arthur Public Utilities Commission Light and Power Department Truck	One man sitting in truck and four men standing at side of truck		P015
<input type="checkbox"/> 80	Four Sided Clock	Construction of movement of a four sided clock for the Public Utilities Commission - photos are numbered 80.1, 80.2 and 80.3. All 3 scanned photographs available.		P005
<input type="checkbox"/> 81	Frederick Francis Burns		June 7, 1934	P005
<input type="checkbox"/> 82	Street Scene	[Intersection of Red River Road - (formerly Arthur Street) & Cumberland Street - Prince Arthur Hotel on left and Pagoda in background		P005
<input type="checkbox"/> 83	Bell Telephone Truck	Bell Telephone Co. standard L. I.-34 - side view - stamped on back of photo - Pringle & Booth Limited Toronto		P015
<input type="checkbox"/> 84	Bell Telephone Truck	Bell Telephone Co. Standard L. I-34 - rear open view - stamped on back of photo - Pringle & Booth Limited, Toronto		P015
<input type="checkbox"/> 85	Port Arthur Midget Hockey League	Group photo	1937-1938	P005
<input type="checkbox"/> 86	Public Utility Body Truck	Stratford Public Utilities Commission Truck made by Truck Engineering Limited, Trailers & Truck Equipment, Woodstock, Ontario		P005
<input type="checkbox"/> 87	Socket Type Meter	Typical installation of socket type meter		P005
<input type="checkbox"/> 88	Socket Type Meter	Typical installation of socket type meter		P015

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 89	Pipes	Large pipes running along ground and under railroad tracks		P005
<input type="checkbox"/> 90	[Pipes]	Large pipes running along ground, can see elevators in the background		P005
<input type="checkbox"/> 91	[Passenger Elevator Car]	4758 - X93143 - passenger elevator car for annex to Quebec Parliament Buildings - stamped on back of photo - Pringle and Booth Limited, Toronto	1936	P015
<input type="checkbox"/> 92	[Control Panel for Elevator]	4747 - X86845 - control panel for two speed alternating current elevator for car switch control - stamped on back - Pringle and Booth Limited, Toronto		P015
<input type="checkbox"/> 93	[Mechanism for Elevator]	#5001 - A4269 - No. 3.5 machine, high speed geared traction type with direct current motor for variable voltage control elevator - stamped on back of photo - Pringle and Booth Limited, Toronto		P015
<input type="checkbox"/> 94	[Mechanism for Elevator]	#5001 - A4269B - No. 3.5 machine, high speed geared traction type with direct current motor for variable voltage control elevator - stamped on back of photo - Pringle and Booth Limited, Toronto		P015
<input type="checkbox"/> 95	[Sign]	Large Wrigley's sign on building and clock over top of sign		P005
<input type="checkbox"/> 96	[Sign]	North-west Laundry sign with a clock on it on street corner		P005

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 97	[Sign]	Large Maple Leaf Tender Sweet Ham sign on side of building with a clock at the top of it		P005
<input type="checkbox"/> 98	[Sign]	Large roadside sign - Welcome to Winnipeg "The Electric City" City Hydro Owned and Operated by its Citizens		P005
<input type="checkbox"/> 99	[Sign]	Sign over bridge - "Welcome to Winnipeg"		P005
<input type="checkbox"/> 100	Street Scene - London, Ontario	Written at top of photo - "After rails were taken up"		P005
<input type="checkbox"/> 101	Street Scene - London, Ontario	Written at top of photo - "No safety zones now needed, bus is close to curb"		P005
<input type="checkbox"/> 102	Richmond Street Looking North, London, Ontario	Written on post card - "Taken before street cars were discarded - note congestion"		P004
<input type="checkbox"/> 103	Dundas Street, London, Ontario	Written on post card - "After trolley lines and street cars were discarded street car tracks since removed"		P004
<input type="checkbox"/> 104	Hazelwood Lake Dam	Unidentified individual overlooking dam		P015
<input type="checkbox"/> 105	Hazelwood Lake Dam	Unidentified individual overlooking dam		P015
<input type="checkbox"/> 106	[Group Photo]	Group of 17 men posed in front of a bus (International Transit Ltd.) - portion of unidentified building behind bus		P005
<input type="checkbox"/> 107	[Group Photo]	Group of men standing and looking about on what looks like a dam		P005
<input type="checkbox"/> 108	[Group Photo]	Group of men seated at a banquet table		P005

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 109	Stan King	Photo of Stan King up on a pole at Coal Harbour, British Columbia	1942	P005
<input type="checkbox"/> 110	Safety Light Installations on Front of Street Cars	Typed at top of photo: #10899 Car #2974 with indicating light and illuminated dash (Comm.) May 28/35	May 28, 1935	P015
<input type="checkbox"/> 111	Safety Light Installations on Front of Street Cars	Typed on side of photo: 11957 street car advertising (Comm.) May 14, 1937	May 14, 1937	P015
<input type="checkbox"/> 112	Hamilton Bus Terminal	Can see coffee shop, counter and people on benches		P015
<input type="checkbox"/> 113	616 Winnipeg Avenue	Damage to dwelling, these photographs are numbered 113.1, 113.2 and 113.3. All 3 scanned photographs available.		P005
<input type="checkbox"/> 114	Current River - Main Dam	Repair work undertaken on the main spillway at Current River - repairs to south 85' of spillway. All 4 scanned photographs available for viewing.	October 1944	P028
<input type="checkbox"/> 115	[Dam]	Photo of a dam and building beside it - looks like same place as Accession 1993-1 Item 116		P016
<input type="checkbox"/> 116	[Dam]	Dam and building beside it - looks like same place as Acc. 1993-01 Item 115		P005
<input type="checkbox"/> 117	[Dam]	Looks like a dam and a building beside it		P005
<input type="checkbox"/> 118	[Construction Site]	Excavation or construction site - looks like a road is being constructed - almost the same photo as Accession 1993-01 Item 119		P005

Note: Negative available when checkmark in box.

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 119	[Construction Site]	Excavation or construction site - looks like a road is being constructed - almost the same photo as Accession 1993-01 Item 118		P005
<input type="checkbox"/> 120	[Group Photo]	Three unidentified well dressed gentlemen standing outside - trees & shrubs in background		P005
<input type="checkbox"/> 121	[Group Photo]	Outdoor photo of eleven well dressed gentlemen		P005
<input type="checkbox"/> 122	[Group Photo]	Outdoor photo - Nineteen unidentified well dressed gentlemen		P005
<input type="checkbox"/> 123	[Group Photo]	Thirty-one unidentified men posed in front of an unidentified building		P005
<input type="checkbox"/> 124	[Construction Site]	Unidentified men looking over some sort of construction area - possibly a dam - looks like it is in same location as Accession 1993-01 Item 125		P005
<input type="checkbox"/> 125	[Construction Site]	Unidentified men looking at area - possibly a dam site - looks like it is in same location as Accession 1993-01 Item 124		P005
<input type="checkbox"/> 126	[Group Photo]	Group of five unidentified men - outside - houses in background		P005
<input type="checkbox"/> 127	[Metal Clad Job]	B978 Metal Clad Job with the oil switch mounted at the rear		P016
<input checked="" type="checkbox"/> 128	[Street Railway]	Street Railway employee stepping out of street railway car - South Belt Hodder Avenue - in window of car - negative available in P010		P016
<input type="checkbox"/> 129	[Street Railway]	Open doors into street railway car		P016

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 130	[Street Railway]	Street Railway tracks, roads, a few houses, car parked on road - looks like same location as Accession 1993-1 Item 131		P016
<input type="checkbox"/> 131	[Street Railway]	Woman stepping out of street car, two men in uniforms in photo as well - looks like same location as Accession 1993-01 Item 131		P016
<input type="checkbox"/> 132	[Bus]	Front view of Model C-36 bus, completed in Fort William Works (Canadian Car & Foundry Co. Ltd.) On back of photo - Model C-36 Photo #1 Sales Office - Bus Division Canadian Car & Foundry Co. Limited, 402 Royal Bank Bldg., Toronto, Ontario		P016
<input type="checkbox"/> 133	[Bus]	Front door side view of Model C-36 Bus, completed in Fort William Works (Canadian Car & Foundry Co. Ltd.) On back of photo - Model C-36 Photo #2 Sales Office - Bus Division Canadian Car & Foundry Co. Limited, 402 Royal Bank Bldg., Toronto, Ontario		P016
<input type="checkbox"/> 134	[Bus]	Driver's side view of Model C-36 Bus, completed in Fort William Works (Canadian Car & Foundry Co. Limited) On back of photo - Model C-36 Photo #3 Sales Office - Bus Division Canadian Car & Foundry Co. Limited, 402 Royal Bank Bldg., Toronto, Ontario		P016

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 135	[Bus]	Inside front section Model C-36 Bus completed in Fort William Works (Canadian Car & Foundry Co. Limited) On back of photo - Model C-36 Photo #4 Sales Office - Bus Division Canadian Car & Foundry Co. Limited, 402 Royal Bank Bldg., Toronto, Ontario		P016
<input type="checkbox"/> 136	[Bus]	View taken from back to front inside Model C-36 Bus completed in Fort William Works (Canadian Car & Foundry Co. Limited) On back of photo - Model C-36 Photo #5 Sales Office - Bus Division Canadian Car & Foundry Co. Limited, 402 Royal Bank Bldg., Toronto, Ontario		P016
<input type="checkbox"/> 137	[Bus]	View taken from front to back inside Model C-36 Bus completed in Fort William Works (Canadian Car & Foundry Co. Limited) On back of photo - Model C-36 Photo #6 Sales Office - Bus Division Canadian Car & Foundry Co. Limited, 402 Royal Bank Bldg., Toronto, Ontario		P016
<input type="checkbox"/> 138	Aguasabon Power Development	Photo display of Aguasabon Power Development		P016
<input type="checkbox"/> 139	Pine Portage Generating Station	Two photo display		P016
<input type="checkbox"/> 140	Orchard Exchange Vault - Toronto	Photos are numbered 140.1, 140.2, 140.3 and 140.4. All 4 scanned photographs available.		P005
<input type="checkbox"/> 141	St. Catherines Exchange	Cable Vault - Photos are numbered 141.1 and 141.2. Both scanned photographs available.	March 29, 1947	P005

Note: Negative available when checkmark in box.

Accession # 1993-01

Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 142	Trolley Car	Buildings in background		P016
<input type="checkbox"/> 143	[Bus]	Bus 106 - North Belt - showing damages from accident - Photos are numbered 143.1 and 143.2. Both scanned photographs available.		P016
<input type="checkbox"/> 144	[Street Railway Vehicle]	Public Utilities Commission Street Railway Department vehicle - looks like it has fallen into a large rut in the road - houses and buildings and unidentified people in photo as well - Photos are numbered 144.1, 144.2 and 144.3. All 3 scanned photographs available.		P005
<input type="checkbox"/> 145	[Presentation]	Gentleman making a presentation to a young boy		P005
<input type="checkbox"/> 146	[Group Photo]	Large group of unidentified gentlemen - some are seated at a banquet table and others are standing at the back of the room		P016
<input type="checkbox"/> 147	[Group Photo]	Group of unidentified gentlemen - some seated and some standing		P016
<input type="checkbox"/> 148	[Group Photo]	Nine unidentified gentlemen, also display relating to Adequate Wiring. Both scanned photographs available.		P016
<input type="checkbox"/> 149	Current River - Onion Lake Area	Aerial view		P016
<input type="checkbox"/> 150	Hazelwood Lake	W.L. 13' 5"	August 6, 1941	P028
<input type="checkbox"/> 151	[Work Site]	Men working on what looks like a dam, ground is snow covered, hills in background - looks like same area as Accession 1993-01 Item 152	February 24, 1938	P005

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 152	[Work Site]	Five unidentified men standing on what looks like a dam, ground is snow covered, man working in background - looks like same area as Accession 1993-01 Item 151		P005
<input type="checkbox"/> 153	[Group Photo]	Five unidentified men standing in front of a wooden cabin, some of the same men are in Accession 1993-01 Item 152	February 1938	P005
<input type="checkbox"/> 154	[Men on Trail]	Men going up a trail, ground is snow covered	February 1938	P005
<input type="checkbox"/> 155	[Work Site]	Men working on what looks like a dam under repair or construction		P005
<input type="checkbox"/> 156	[Work Site]	Looks like a dam site under repair or construction		P005
<input type="checkbox"/> 157	[Work Site]	Two men working at what looks like a creek entrance to a larger body of water, train in background		P005
<input type="checkbox"/> 158	[Work Site]	Looks like a dam site under repair or construction		P005
<input type="checkbox"/> 159	[Men on Dam]	Seven unidentified men standing on a dam, a few of them look like they could be guards		P016
<input type="checkbox"/> 160	[Men on Dam]	Five unidentified men standing on dam, four of them look like guards, small shack in foreground		P016
<input type="checkbox"/> 161	[Men on Dam]	Eight unidentified men standing about on dam, four of them look like guards		P016
<input type="checkbox"/> 162	[Work Site]	Men working on a dam under repair or construction, snow on ground		P016

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 163	[Current River]	Aerial photo		P016
<input type="checkbox"/> 164	[Work Site]	Dam under repair or construction - photos are numbered 164.1 and 164.2. Both scanned photographs available.	1949	P005
<input type="checkbox"/> 165	[Work Site]	Deterioration of dam wall and reinforcing of same - photos are numbered 165.1 and 165.2. Both scanned photographs available.	1949	P005
<input type="checkbox"/> 166	[Current River]	View looking down river	1949	P005
<input type="checkbox"/> 167	[People on Dock]	Three unidentified adults, two men, one woman and a child on a dock	1949	P005
<input type="checkbox"/> 168	Onion Lake	Three different views of dam - photos are numbered 168.1, 168.2 and 168.3	Aug. 6, 1941	P028
<input type="checkbox"/> 169	[Work Site]	Three different views of dam under repair - photos are numbered 169.1, 169.2 and 169.3	Sep. 8, 1938	P028
<input type="checkbox"/> 170	[Dam]	Three different views of dam - possibly Current River - showing deterioration and repair work - photos are numbered 170.1, 170.2 and 170.3		P028
<input type="checkbox"/> 171	[Dam]	Three different views of dam - photos are numbered 171.1, 171.2 and 171.3		P028
<input type="checkbox"/> 172	[Dam]	Three different views - two showing views of river and one showing dam site - photos are numbered 172.1, 172.2 and 172.3	August 1949	P028

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 173	[Dam]	Three different views of dam under repair - photos are numbered 173.1, 173.2 and 173.3	August 1949	P028
<input type="checkbox"/> 174	[River]	Two different views - photos are numbered 174.1 and 174.2	Sep. 17	P028
<input type="checkbox"/> 175	Ray Lake Watershed	Aerial photo showing Ray Lake and Steepledge Lake		P016
<input type="checkbox"/> 176	Proposed Dam on Current River	Aerial photo re proposed dam on Current River to be located approximately 1.6 miles below Onion Lake	[1949]	P016
<input type="checkbox"/> 177	[Transit Uniform]	Front and back view - photos are numbered 177.1 and 177.2. Both scanned photographs available.		P005
<input type="checkbox"/> 178	[Transit Uniform]	Overcoat uniform - front, side and back view - photos are numbered 178.1, 178.2 and 178.3. All 3 scanned photographs available.		P005
<input type="checkbox"/> 179	[Gorham Township]	Aerial photo - 1/47C-4824A 935-4 - South half Lot 6 & 7, Concession 111		4861
<input type="checkbox"/> 180	[Gorham Township]	Aerial photo - 1/47C-4824A 935-5 - South half Lot 6 & 7, Concession 111		4861
<input type="checkbox"/> 181	King Model H-132CW Truck	Side and rear views, - Negative No. 1153B & 1153E - photos are numbered 181.1 and 181.2. Both scanned photographs available.		P016
<input type="checkbox"/> 182	King Model H-132CW Truck	Truck with unidentified individual on raised hydraulic platform, other individuals watching, the word "Chicago" on back of photo		P005

Note: Negative available when checkmark in box.

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 183	Truck	King Model H-132 line construction body, M9-18B winch and Model H-132-CT body and tower platform equipment, Negative No. 1014A		P016
<input type="checkbox"/> 184	[Group Photo]	Nineteen unidentified men standing and kneeling in front of a train		P016
<input type="checkbox"/> 185	[Hydro Pole]	Bent hydro pole - cause of H. T. outage on Sunday, October 19. Both scanned photographs available.		P005
<input type="checkbox"/> 186	[Substation]	Different views of various equipment and apparatus inside a substation - photos are numbered 186.1, 186.2, 186.3, 186.4 and 186.5 - looks like same place as Accession 1993-01 Item 187. All 5 scanned photographs available.		P016
<input type="checkbox"/> 187	[Pumping Station]	Inside a pumping station - possibly Bare Point - photos are numbered 187.1 and 187.2 - looks like the same place as in Accession 1993-01 Item 186. Both scanned photographs available.		P005
<input type="checkbox"/> 188	Substation	Canadian General Electric Co. Limited 8386 3750 KVA - 44000 to 4000 volt, package substation - (front view) - Filing No. 5155 - September, 1947	September 1947	P016
<input type="checkbox"/> 189	Onion Lake	Repair work on dam	Nov. 23, 1953	P016
<input type="checkbox"/> 190	Onion Lake	Repair work on dam	Nov. 23, 1953	P016
<input type="checkbox"/> 191	Onion Lake	Repair work on dam	Nov. 23, 1953	P016
<input type="checkbox"/> 192	Onion Lake	Repair work on dam	Nov. 23, 1953	P016

Note: Negative available when checkmark in box.

Accession # 1993-01 Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 193	Current River Watershed	Photographs numbered 1 to 7 on back - different views along Current River Watershed - photos are numbered 193.1, 193.2, 193.3, 193.4, 193.5, 193.6 and 193.7. All 7 scanned photographs available for viewing.		P027
<input type="checkbox"/> 194	Telephone	E Telco automatic telephone		P016
<input type="checkbox"/> 195	Onion Lake Dam	View of dam	Feb. 12, 1954	P005
<input type="checkbox"/> 196	Onion Lake Dam	Close up view of dam	Feb. 12, 1954	P005
<input type="checkbox"/> 197	Onion Lake Dam	View of dam area	Feb. 12, 1954	P005
<input type="checkbox"/> 198	Onion Lake Dam	Four unidentified men standing in front of two cars - building and a truck in the background	Feb. 12, 1954	P005
<input type="checkbox"/> 199	[Group Photo]	Four unidentified gentlemen dressed in suits	Mar. 1, 1954	P016
<input type="checkbox"/> 200	[Underground Lines]	Some sort of digging showing underground lines	April 1954	P016
<input type="checkbox"/> 201	Transformer Trailer Body			P016
<input type="checkbox"/> 202	Morrison Service Body	Model 700-6 for half ton chassis - six compartments - twenty-five square feet of floor loading area - Canadian Distributors: Utility Body Company of Canada, 1330 Bloor St. West, Toronto 4, Ontario KE 9438		P004
<input type="checkbox"/> 203	Fare Register			P016
<input type="checkbox"/> 204	Truck	Side and rear views showing compartments in body - photos are numbered 204.1 and 204.2. Both scanned photographs available.		P016

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 205	Switchboard Operators	Two operators working at a switchboard		P005
<input type="checkbox"/> 206	Switchboard Operators	Two operators working at a switchboard		P016
<input type="checkbox"/> 207	Truck			P016
<input type="checkbox"/> 208	[Group Photo]	Group of unidentified gentlemen outside of Rainy Lake Hotel - On back of photo: Dist. #3 meeting, Kenora, 1957	1957	P016
<input type="checkbox"/> 209	Northern Wood Preservers	Elevators and Lake Superior in background		P009
<input type="checkbox"/> 210	Telemeter	Operation of telemeter - photos are numbered 210.1, 210.2 and 210.3. All 3 scanned photographs available for viewing.		P016
<input type="checkbox"/> 211	[Building Entrance]	Entrance to a building - possibly Public Utilities Commission Building		P016
<input type="checkbox"/> 212	[Score Board]	Two women and three men looking at a score board at Prince George banquet		P016
<input type="checkbox"/> 213	[Score Board]	One individual holding up a new Westminster Score Board - others seated at a		P016
<input type="checkbox"/> 214	[Score Board]	Two individuals holding up a poster and score board re Victoria Banquet Contest		P016
<input type="checkbox"/> 215	[Bus]	Two views of a forty-five passenger bus - photos are numbered 215.1 and 215.2. Both scanned photographs available.		P005

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input checked="" type="checkbox"/> 216	Edmund A. Vigars	[Manager of the Public Utilities Commission] - photos are numbered 216.1, 216.2 and 216.3. All 3 scanned photographs available. - negative available in P010		P005
<input type="checkbox"/> 217	1891 Generating Station	Can see wording "Public Utilities Commission" on one of the buildings		P005
<input type="checkbox"/> 218	Substation	8000 KVA.23 to 4.16KV Substation		P005
<input type="checkbox"/> 219	Transformer Installation	A clean transformer installation		P005
<input type="checkbox"/> 220	4.16KV Circuit on Steel Trolley Poles			P005
<input type="checkbox"/> 221	Transformer	45KVA to 120/208 volts transformer at small school		P005
<input type="checkbox"/> 222	[Service Centre Opening]	People looking at display of various types of lights	1962-1963	P005
<input type="checkbox"/> 223	[Service Centre Opening]	People standing about - looks like they are watching an employee at a display area	1962-1963	P005
<input type="checkbox"/> 224	[Service Centre Opening]	People going through a display area	1962-1963	P005
<input type="checkbox"/> 225	[Service Centre Opening]	Three unidentified men looking at a traffic signal control display	1962-1963	P005
<input type="checkbox"/> 226	[Service Centre Opening]	Unidentified worker seated at a bench working on cables	1962-1963	P005
<input type="checkbox"/> 227	[Service Centre Opening]	People observing as a worker moves an object along a cable	1962-1963	P005
<input type="checkbox"/> 228	[Service Centre Opening]	People observing as worker shows them some sort of cable apparatus	1962-1963	P005

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 229	[Service Centre Opening]	Three vehicles parked in a garage	1962-1963	P005
<input type="checkbox"/> 230	[Service Centre Opening]	Two men looking at a waterworks display	1962-1963	P005
<input type="checkbox"/> 231	[Service Centre Opening]	Two people playing bagpipes in costume while people are going up stairs in to a building	1962-1963	P005
<input type="checkbox"/> 232	Telephone	Photo of telephone - Ref. No. 6336-1		P016
<input type="checkbox"/> 233	Code-A-Phone	Reference No. 6112		P016
<input type="checkbox"/> 234	Telephone	Northern Electric - made in Canada - Ref. No. 6336-2		P016
<input type="checkbox"/> 235	[Telephone Apparatus]	Northern Electric Telephone Apparatus - Ref. No. 6336-4		P016
<input type="checkbox"/> 236	[Telephone]	Unidentified individual working at a desk - telephone with speaker system on desk - Ref. No. 6336-7		P016
<input type="checkbox"/> 237	Telephone	Rapidial Telephone - Ref. No. 6336-10		P016
<input type="checkbox"/> 238	[Keefer Terminal]	New terminal [possibly Keefer Terminal] showing the elevators, ore dock and City in the background		P016
<input type="checkbox"/> 239	[Bus]	Front passenger side view		P005
<input type="checkbox"/> 240	[Bus]	Rear passenger side		P016
<input type="checkbox"/> 241	Murillo Exchange Official Opening	Woman sitting at switchboard - Mrs. Ida McKenzie - on back of photo - photos are numbered 241.1 and 241.2. Both scanned photographs available.	Dec. 1, 1962	P005

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 242	Murillo Exchange Official Opening	Person standing in front of building - sign behind him says "Murillo Telephone Exchange" - Geo. Hunter - on back of photo	Dec. 1, 1962	P005
<input type="checkbox"/> 243	Murillo Exchange Official Opening	Fred Rolley & G. A. Wilson - names on back of photo	Dec. 1, 1962	P005
<input type="checkbox"/> 244	Murillo Exchange Official Opening	W. McDougall, E. A. Vigars and R. Clarborough	Dec.1, 1962	P005
<input type="checkbox"/> 245	Murillo Exchange Official Opening	Left to right - Mike Valigrosky, C. Potter and C. Fenton	Dec. 1, 1962	P005
<input type="checkbox"/> 246	Murillo Exchange Official Opening	J. Currie, C. Potter, R. L. Ditmars and W. McDougall	Dec. 1, 1962	P005
<input type="checkbox"/> 247	Murillo Exchange Official Opening	M. Valigrosky	Dec. 1, 1962	P005
<input type="checkbox"/> 248	Murillo Exchange Official Opening	P. Vaillant, J. Currie and E. A. Vigars	Dec. 1, 1962	P005
<input type="checkbox"/> 249	Murillo Exchange Official Opening	C. Potter, C. Fenton, P.Vaillant, E. A. Vigars & J. Currie - one gentleman is on the phone and the others are looking on	Dec. 1, 1962	P005
<input type="checkbox"/> 250	Murillo Exchange Official Opening	Left to right - H. Henry, J. Holmes, C. Potter, C. Fenton, P. Vaillant and E. A. Vigars - one gentleman is on the phone while the others are observing	Dec. 1, 1962	P005
<input type="checkbox"/> 251	Murillo Exchange Official Opening	Left to right - P. Vaillant and E. A. Vigars	Dec. 1, 1962	P005
<input type="checkbox"/> 252	Murillo Exchange Official Opening	Group Photo in front of building - left to right - F. Dewhurst, C. Boland, E. A.Vigars, A. Podd, H. Henry, F. Rolley and J. Holmes	Dec. 1, 1962	P005
<input type="checkbox"/> 253	Murillo Exchange Official Opening	G. A. Wilson and W. McDougall	Dec. 1, 1962	P005

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 254	Murillo Exchange Official Opening	Left to right - J. E. Lawrence, P. Vaillant, M. Valigrosky and W. Windsor	Dec. 1, 1962	P005
<input type="checkbox"/> 255	Murillo Exchange Official Opening	J. Currie and E. A. Vigars - J. Currie on phone	Dec. 1, 1962	P005
<input type="checkbox"/> 256	Murillo Exchange Official Opening	Left to right as shown on back of photo - E. Cousins, ?, R. Clarborough, C. Potter, A. Podd, H. Henry, G. Hunter, ?	Dec. 1, 1962	P005
<input type="checkbox"/> 257	Murillo Exchange Official Opening	Two unidentified gentlemen - on back of photo - News Chronicle Reporters	Dec. 1, 1962	P005
<input type="checkbox"/> 258	Murillo Exchange Official Opening	Left to right - W. Windsor, H. Henry and E. Cousins	Dec. 1, 1962	P005
<input type="checkbox"/> 259	Murillo Exchange Official Opening	W. Windsor, N. E. Installer	Dec. 1, 1962	P005
<input type="checkbox"/> 260	Murillo Exchange Official Opening	H. Henry, C. Potter and P. Vaillant	Dec. 1, 1962	P005
<input type="checkbox"/> 261	Murillo Exchange Official Opening	Fred Dewhurst and E. A. Vigars - standing outside of Murillo Telephone Exchange	Dec. 1, 1962	P005
<input type="checkbox"/> 262	Murillo Exchange Official Opening	Harvey Gorton - on telephone	Dec. 1, 1962	P005
<input type="checkbox"/> 263	Murillo Exchange Official Opening	Harvey Gorton - on telephone	Dec. 1, 1962	P005
<input type="checkbox"/> 264	[Bus]	Inside of bus taken from the front looking towards the back - On back of photo - Serial #B62-2145-1, Description - Transit, The Flxible Company, Loudonville, Ohio		P016

Note: Negative available when checkmark in box.

Accession # 1993-01

Dept./ Division: Public Works

Series 88 Port Arthur Public Utilities Commission Files

A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 265	[Bus]	Outside driver's side of bus, unidentified building in background - On back of photo - Serial # B62-2158, Description - Transit, The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 266	[Bus]	Outside door side of bus - driver and a few passengers in the bus, unidentified buildings in the background - On back of photo - Serial #B62-2164, Description - Transit, the Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 267	[Bus]	Outside front section of bus - "The Flxible Co." on sign on bus - On back of photo - Serial #B62-2191, Description - Transit 102" W, The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 268	[Engine]	Serial #B62-2210, Description - Transit Engine, The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 269	[Bus]	Inside of bus looking towards back, On back of photo - Serial #B63-2288-1, Description - 38 pass. Transit Int., The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 270	[Bus]	Inside of bus looking towards front, On back of photo - Serial #B63-2288-2, Description - 38 Pass. Transit Int., The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 271	[Bus]	Outside of bus taken from door side, On back of photo - Serial #B63-2291, Description - 33' Transit, The Flxible Company, Loudonville, Ohio		P016

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 272	[Bus]	Outside of bus taken from Driver's side, On back of photo - Serial #B63-2293, Description - 33' Transit, The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 273	[Bus]	Unidentifiable part of bus - on back of photo - Serial #B63-2287, Description - 33' Transit, The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 274	[Bus]	Two women going into a bus		P009
<input type="checkbox"/> 275	Public Utilities Commission Building			P016
<input checked="" type="checkbox"/> 276	Public Utilities Commission Building	Photo taken at night displaying lit Christmas lights - negative available in P010	1964	P016
<input checked="" type="checkbox"/> 277	Welcome Arch	Arch reads: "Welcome to Port Arthur" Electric Living at Low Cost - photos are numbered 277.1 and 277.2 - negative available in P010	1965	P016
<input type="checkbox"/> 278	Public Utilities Offices (Renovated Facilities) Formal Opening	#1 on back of photo - three unidentified individuals - two men and one woman, probably an employee, looking at a display, possibly relating to street railway	Oct. 31, 1964	P005
<input type="checkbox"/> 279	Public Utilities Offices (Renovated Facilities) Formal Opening	#2 on back of photo - five unidentified individuals - one man and four women, two of the women could be employees	Oct. 31, 1964	P005
<input type="checkbox"/> 280	Public Utilities Offices (Renovated Facilities) Formal Opening	#25 on back of photo - Seven or eight people watching as an unidentified woman is displaying a stove	Oct. 31, 1964	P005

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 281	Public Utilities Offices (Renovated Facilities) Formal Opening	#26 on back of photo - numerous people looking at offices	Oct. 31, 1964	P005
<input type="checkbox"/> 282	Public Utilities Offices (Renovated Facilities) Formal Opening	#27 on back of photo - about eight people going through offices - two employees standing by	Oct. 31, 1964	P005
<input type="checkbox"/> 283	Public Utilities Offices (Renovated Facilities) Formal Opening	#28 on back of photo - people sitting having coffee and employees assisting	Oct. 31, 1964	P005
<input type="checkbox"/> 284	Public Utilities Offices (Renovated Facilities) Formal Opening	#29 on back of photo - people walking through offices looking at various lighting equipment	Oct. 31, 1964	P005
<input type="checkbox"/> 285	Public Utilities Offices (Renovated Facilities) Formal Opening	#30 on back of photo - people looking at displays	Oct. 31, 1964	P005
<input type="checkbox"/> 286	Public Utilities Offices (Renovated Facilities) Formal Opening	#31 on back of photo - four people looking at displays on desk and two employees behind desk	Oct. 31, 1964	P005
<input type="checkbox"/> 287	Public Utilities Offices (Renovated Facilities) Formal Opening	#32 on back of photo - five people looking at a display - two employees behind desk look like they are explaining something	Oct. 31, 1964	P005
<input type="checkbox"/> 288	Public Utilities Offices (Renovated Facilities) Formal Opening	#33 on back of photo - People looking at different types of telephones	Oct. 31, 1964	P006
<input type="checkbox"/> 289	Public Utilities Offices (Renovated Facilities) Formal Opening	#34 on back of photo - numerous people walking through offices - can see various displays set up along walls	Oct. 31, 1964	P006
<input type="checkbox"/> 290	Public Utilities Offices (Renovated Facilities) Formal Opening	#35 on back of photo - people looking at stoves and automatic washers and dryers	Oct. 31, 1964	P006

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 291	Public Utilities Offices (Renovated Facilities) Formal Opening	#37 on back of photo - people looking at accounting equipment	Oct. 31, 1964	P006
<input type="checkbox"/> 292	Public Utilities Offices (Renovated Facilities) Formal Opening	#38 on back of photo - numerous people looking at accounting equipment	Oct. 31, 1964	P006
<input type="checkbox"/> 293	Public Utilities Offices (Renovated Facilities) Formal Opening	#39 on back of photo - people coming in to building	Oct. 31, 1964	P006
<input type="checkbox"/> 294	Public Utilities Offices (Renovated Facilities) Formal Opening	#40 on back of photo - people walking through offices	Oct. 31, 1964	P006
<input type="checkbox"/> 295	Public Utilities Offices (Renovated Facilities) Formal Opening	#41 on back of photo - people looking at telephone display	Oct. 31, 1964	P006
<input type="checkbox"/> 296	Public Utilities Offices (Renovated Facilities) Formal Opening	#42 on back of photo - people looking at a safety display	Oct. 31, 1964	P006
<input type="checkbox"/> 297	Public Utilities Offices (Renovated Facilities) Formal Opening	#43 on back of photo - people looking at a display - can see photographs of buses	Oct. 31, 1964	P006
<input type="checkbox"/> 298	Bus Advertising	Advertising on bus		P004
<input type="checkbox"/> 299	Transit Bus	Taken from door side - on back of photo - Canadair Limited, Montreal, Neg. No. 47480		P016
<input type="checkbox"/> 300	Transit Bus	Driver's side view - on back of photo - Canadair Limited, Montreal, Neg. No. 47482		P016
<input type="checkbox"/> 301	Transit Bus	Inside of bus looking towards rear - on back of photo - Canadair Limited, Montreal, Neg. No. 47486		P016
<input type="checkbox"/> 302	Transit Bus	Inside of bus looking towards front - on back of photo - Canadair Limited, Montreal, Neg. No. 47487		P016

Note: Negative available when checkmark in box.

Accession # 1993-01**Dept./ Division: Public Works****Series 88 Port Arthur Public Utilities Commission Files****A**

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 303	Transit Coach	Door side view - on back of photo - Canadair Limited, Montreal, Neg. No. 53540		P016
<input type="checkbox"/> 304	[Truck]	Truck with trump giraffe aerial platform - on side of truck - Trump Brampton - truck is parked in front of a Canadian Tire Store		P016
<input type="checkbox"/> 305	Lot 17 Juniper Drive	Possible eave encroachment		P006
<input type="checkbox"/> 306	Lot 43 Juniper Drive	Possible eave encroachment		P006
<input type="checkbox"/> 307	[Steam Engine]	[Original steam engine - in 1885, along with the electric current generator, provided the first electric lighting west of the Great Lakes]	Feb. 1967	P006
<input type="checkbox"/> 308	[Generator]	[Original electric current generator - in 1885, along with the steam engine, provided the first electric lighting west of the Great Lakes]	Feb. 1967	P006
<input type="checkbox"/> 309	[Steam Engine & Electric Current Generator]	Side view and plan view of the original steam engine and electric current generator which in 1885 provided the first electric lighting west of the Great Lakes - photos are numbered 309.1 and 309.2		P027
<input type="checkbox"/> 310	[Steam Engine & Electric Current Generator]	Side view of original steam engine and electric current generator - photos are numbered 310.1 and 310.2. Both scanned photographs available for viewing.	Sep. 1966	P006
<input type="checkbox"/> 311	[Steam Engine and Electric Current Generator]	Plan view of original steam engine and electric current generator	Sep. 1966	P006

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 312	[Steam Engine and Electric Current Generator]	Side view of the original steam engine and electric current generator	Sep. 1966	P006
<input type="checkbox"/> 313	[Steam Engine]	Original Steam Engine	Sep. 1966	P006
<input type="checkbox"/> 314	[Electric Generator]		Feb. 1967	P006
<input type="checkbox"/> 315	[Safety Plaque]	Commissioner R. V. Wilmot receiving plaque donated by the Canadian Highway Safety Council on behalf of Port Arthur Transit winning first place in the 1966 Annual Traffic Safety Competition for systems serving populations of less than 200,000. Improvement factor was 14.7%. Plaque being presented by Mr. Philip J. Farmer, Mayor Reg. Dawson and Bill Purdy of Ottawa.	Tuesday, June 20, 1967	P016
<input type="checkbox"/> 316	[Steam Engine & Electric Current Generator]	Side view and plan view of the original steam engine and electric current generator which in 1885, provided the first electric lighting west of the Great Lakes - photos are numbered 316.1 and 316.2		P027
<input type="checkbox"/> 317	[Lot 156 Woodside St.]	Encroachment of easement Lot 156 Woodside St. - photos are numbered 317.1, 317.2 and 317.3. All 3 scanned photographs available for viewing.		P006
<input type="checkbox"/> 318	[Bus]	On back of photo - Serial #B65-2520, Description - 35' Transit, The Flxible Company, Loudonville, Ohio		P016
<input type="checkbox"/> 319	[Bus Shelter]	On back of photo - the Dumont Aluminum Ltd., 709 Main Street, West, Hamilton, Ont.		P004
<input type="checkbox"/> 320	[Bus Advertising]			P004

Note: Negative available when checkmark in box.

Accession # 1993-01	Dept./ Division: Public Works
Series 88 Port Arthur Public Utilities Commission Files	A

ITEM #	PHOTO TITLE	SUBJECT	DATE(S)	LOCATION
<input type="checkbox"/> 321	[Bus Advertising]	Photo taken at night under high intensity street lighting		P004
<input type="checkbox"/> 322	Electrically Heated Home	108 Gibbon Street - electrically heated home - photos are numbered 322.1 and 322.2. Both scanned photographs available for viewing.	Jan. 1968	P006
<input type="checkbox"/> 323	Electrically Heated Home	Inside Kitchen of 108 Gibbon St. - unidentified woman loading dishes into dishwasher - on back of photo - 108 Gibbon St., February 1968 for News Chronicle Special - Bride's Addition	Feb. 1968	P006

Note: Negative available when checkmark in box.