

26 Nugent St.



Architectural Analysis:

26 Nugent St.

Significance Rating: A Compatibility Rating: A Materials Rating: B

Year Built:

- 1908

Original Owner:

- Louis Walsh

Builder/Architect:

-

Building orientation on Property:

- The house is situated on the northerly side of the property and faces McVicar St.

Current Building Use:

- Home

Exterior Building Design / Materials:

- 1 ½ storey
- The main floor's exterior walls are red brick except on the backside of the house (south side) where wood shingles are used to cover some of areas
- Red, cut stone is used at base of the house
- Front porch/verandah and gable on the northeast corner of the house is angled to face McVicar Creek. This unique design gives the overall shape of the house a pentagon formation
- The house has a sunroom and a two storey addition on the south side

- Wood shingles cover the exterior walls of the second storey

Roof Design/Materials:

- The roof is a cross gable design type
- Asphalt shingles
- The gable on the north-east corner is on a 45 degree angle compared to the main roof gable
- Shed roof designs cover the porch, sunroom and the two storey addition
- Wood shingles cover the gable ends

Window Design:

- Windows are casement types in varying sizes. Some are single hung types

- A square window turned on a 45 degree angle is located near the top of the angled gable

- Sandstone window sills adorn some of the windows

Additional Details:

- The home has two brick chimneys
- The house is poorly maintained and signs of aging are evident
- The shrubbery on the McVicar St. side of the home blocks the view of the front on the house
- A brick garage which once might have been the stable exists on the south side of the property