

288 Harrington Ave.



Architectural Analysis:

288 Harrington Ave.

Significance Rating: A Compatibility Rating: A Materials Rating: A

Year Built:

- 1907

Original Owner:

- Thomas N. Andrew

Builder/Architect:

-

Building orientation on Property:

- This home is set back on this corner lot property

Current Building Use:

- Home – might have apartments inside

Exterior Building Design / Materials:

- 2 ½ Storey
- The exterior walls are brick veneer
- The front south-east corner of the home is angled to face the corner of the property.
- Detailed brickwork along the upper portions of the east and south walls – recessed and corbelled designs
- Vertical brickwork over the top of each window
- Arched brickwork frames an arched window on the west side of the house

- Sandstone window sills

Roof Design/Materials:

- The main portion of the roof is a pyramidal design, but has two gabled hips on the south and west sides of the home
- Gabled dormers are located at the front (south) and west sides of the house as well
- Asphalt shingles on main roof
- Gable ends are covered with asphalt shingles
- There is a small gable that frames the top of the angled south-east corner of the home and the gable

end is covered with wood shingles in a geometric pattern

Window Design:

- This building has a variety of different windows – double and single hung, sliding, casement, fixed, ribbon, arched, and block type designs

Additional Details:

- This home has an intricately designed chimney with a corbelled top
- The angled south east corner of the home makes the house unique in the area